



Ordering code



When ordering parts, please indicate the related part number to be found in the price list.

By high regulating speed of the valve inadmissible strong brake forces can conduct on the actuator. Remedy: Throttling of the exhaust air or choosing of a bigger size of actuator type.



1 Seeger circlip ring

- 2 Washer
- 3 O-ring
- 4 piston guidance ring
- 5 piston
- 6 cap gasket
- 7 сар
- 8 cap screw
- 9 guidance segment
- 10 casing
- 11 pinion
- . 12 O-ring
- 13 O-ring
- 14 upper sliding ring
- 15 lower sliding ring
- 16 spring
- 17 O-ring
- 18 cap nut
- 19 set screw
- 20 piston stopper rod
- 21 O-ring
- 22 guide bush
- 23 seeger circlip ring
- 24 washer

Spare part kits

<u>Spare part kit no. 1</u> Sealing set, comprising (3) (6) (12) (13) (17) (21)

 $\frac{\text{Spare part kit no. 2}}{\text{Guide part set,}}$ comprising (4) (9) (14) (15)

 Spare part kit no. 3

 Cap complete,

 comprising 6 (7) (8) (17) (18) (19) (24)

 for size 049 comprising: (17) (18) (19)

 $\frac{\text{Spare part kit no. 4}}{\text{Piston complete,}}$ comprising (3) (4) (5) (9)

 Spare part kit no. 4-BE

 Piston complete, BE-version (left), comprising (3) (4) (5) (9)

 Piston complete, BE-version (right), comprising (3) (4) (5a) (9) (20) (21) (22) (23)

 Spare part kit no. 5

 Pinion complete,

 comprising 1
 2
 11
 12
 13
 14
 15