



SPRING RETURN ACTUATOR (ASR)

DOUBLE ACTING ACTUATOR (ADA)

471	1	Slip Washer
119	2	O-Ring
118	2	O-Ring
111	1	O-Ring
110	1	O-Ring
109	2	O-Ring
26	1	Lower Pinion Bearing
25	2	Side Guide
24	2	Plug Air Stop
10	1	Upper Pinion Bearing
6	2	Slide Piston
5	1	Soft Pinion Washer
POS.	QUAN.	DENOMINATION

